

Table

Stadox HS Hardener	Normal Drying	Accelerated Drying
Fast		Hardener HS 5-15 Hardener HS 15-25
Slow		Hardener HS 20-30 Hardener HS 25-40